Oil Field Environmental Incident Summary

Responsible Party: Whiting Oil and Gas

Well Operator: WHITING OIL AND GAS CORPORATION

Well Name: ZALESKY 14-8PH

Field Name: NORTH CREEK Well File #: 24663

Date Incident: 2/13/2014 Time Incident: 16:00 Facility ID Number:

County: STARK Twp: 140 Rng: 98 Sec: 8 Qtr: SW SW

Location Description: Majority of spill remained on site with a small amount (estimated less than 1

gallon) misted off location to the west.

Submitted By: Brian Wurm Received By:

Contact Person: Rafe Espinoza

1700 BROADWAY STE 2300

DENVER, CO 80290

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:0.5 MilesDistance Nearest Water Well:0.5 Miles

Type of Incident: Blowout

Release Contained in Dike: No Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units	
Oil	7	barrels	0	barrels	7	barrels	
Brine	0	barrels	0	barrels	0	barrels	
Other	0	barrels	0	barrels			

Description of Other Released Contaminant:

Inspected: Written Report Received: 1/7/2016 Clean Up Concluded: 2/13/2014

Risk Evaluation:

None noted

Areal Extent:

Approximately 20 feet by 20 feet

Potential Environmental Impacts:

To be determined

Action Taken or Planned:

Clean up crew was brought in and pushed impacted snow off site back on location. Remaining fluids and impacted material will be removed and taken to appropriate landfill.

Wastes Disposal Location: Impacted material and fluids recovered with material will be taken to appropriate landfill.

Agencies Involved:

Updates

Date: 2/14/2014 Status: Reviewed - Follow-up Required Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a reported blowout (more likely a treater popoff valve), sprayed off location. Followup is necessary.

Date: 2/25/2014 Status: Inspection Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location at 10:05 2/25/14.

No visible sign of spill at location. The site currently has a workover rig on location.

No followup necessary.